



## ITALVIBRAS Stock List

Part No : (US REFERENCE NUMBER) - MVSI 12-20100- (MVSI 10/10000-S02) EU-  
REFERENCE NUMBER

Part No : 10/1110-S08

Part No : 10/2610-1/4"390 obsolete, replaced by MVSI 10/2610-S02

Part No : 15/200

Part No : 15/400

Part No : 15/400-S02

Part No : 1543035

Part No : 3/800-S02-T

Part No : 600312A

Part No : 600381 MVSI 3/800-S02

Part No : 600449H

Part No : 601136C

Part No : 601219A

Part No : 601329A

Part No : 601358A

Part No : 601413A

Part No : 601524A

Part No : 601524C

Part No : 602134F

Part No : 602167C

Part No : 602380

Part No : A58-601219A

Part No : A58-601221A

Part No : BEARING COVER (No: 46) FOR MVSI 10/9000 S90

Part No : CD 12-6020-APR

Part No : CDX 075/1310-G/D

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web:  
<http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : CDX 075/150-G/D  
Part No : CDX 075/2110-G/D  
Part No : CDX 075/22000-G  
Part No : CDX 075/250-G/D  
Part No : CDX 075/3110-G/D  
Part No : CDX 075/400-G/D  
Part No : CDX 075/660-G/D  
Part No : CDX 075/910-G/D  
Part No : CDX 10/100-G/D  
Part No : CDX 10/1110-G/D  
Part No : CDX 10/1610-G/D  
Part No : CDX 10/200-G/D  
Part No : CDX 10/22000-G  
Part No : CDX 10/2610-G/D  
Part No : CDX 10/310-G/D  
Part No : CDX 10/3810-G/D  
Part No : CDX 10/40-G/D  
Part No : CDX 10/550-G/D  
Part No : CDX 10/810-G/D  
Part No : CDX 15/1100-G/D  
Part No : CDX 15/1410-G/D  
Part No : CDX 15/1710-G/D  
Part No : CDX 15/2000-G/D  
Part No : CDX 15/2410-G/D  
Part No : CDX 15/3810-G/D  
Part No : CDX 15/5010-G/D  
Part No : CDX 15/700â€™G/D  
Part No : CDX 3/1100-G/D  
Part No : CDX 3/1500-G/D  
Part No : CDX 3/2100-G/D  
Part No : CDX 3/2300-G/D  
Part No : CDX 3/300-G/D  
Part No : CDX 3/3200-G/D  
Part No : CDX 3/4700-G/D  
Part No : CDX 3/500-G/D

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : CDX 3/800-G/D  
Part No : CDX15-2700 (PN 9870516 ), 400V, 50Hz, 1.75 HP Kit consisting of:  
Part No : CDX15/1100-G MVE1100/15D- 50A0  
Part No : CDX15/200-G/D  
Part No : CDX15/2000-G MVE2400/15D- 60A1  
Part No : CDX15/2410-G MVE2500/15D- 70A0  
Part No : CDX15/400-G/D  
Part No : CDX15/550-G/D  
Part No : CDX18-5900  
Part No : CES09.0001X  
Part No : CFV 037P 42V  
Part No : HY81 0757900-S90 Serie AA- obsolete, replaced by MVSI 075/910-S08  
Part No : IEC 60034-1 LCIE05 ATEX 6163X  
Part No : ITV-VR/2510-V  
Part No : Item 23 for MVSI 10/800-S90-TS2 obsolete  
Part No : Item 3 for MVSI 10/800-S90-TS2 obsolete  
Part No : LMD 10/16000-L1860  
Part No : LMD 15/8600-L1860  
Part No : Lagerflansch f. MVSI 15/7000-S02  
Part No : Lagerschild f. MVSI 10/810-S08  
Part No : M 3/205-S02 400 V, 50 Hz, 3000 min-1  
Part No : M 3/65-S02, 115 V, 60 HZ, 3600 RPM  
Part No : M3/105-S02  
Part No : M3/20 " S02  
Part No : M3/20-S02  
Part No : M3/20-S02, 110/115 V  
Part No : M3/20-S02, 220/240 V  
Part No : M3/20-S02, 220/240 V, 50/60 Hz, 3000/3600 min-1  
Part No : M3/4-S02  
Part No : M3/45-S02  
Part No : M3/500-S02, 400 V, 50 Hz, 3000 min-1  
Part No : M3/65-S02  
Part No : M3/65 " S 02  
Part No : M4-05-18O-V-KS  
Part No : M7-25-18O-V-KS

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web:  
<http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MTF 15/3810-S02-VRS  
Part No : MTF 3/200-S02  
Part No : MTF 3/650-S02  
Part No : MTF3-65-S02  
Part No : MVB 1510 15  
Part No : MVB 18-7000-FLC  
Part No : MVB 4500/1571  
Part No : MVCC 3/1200  
Part No : MVCC 3/1200, 24 V  
Part No : MVCC 3/200-S02  
Part No : MVE 2600/12D-75A0  
Part No : MVE 50-2  
Part No : MVS 05/770 MP-S90 obsolete, replacement MVSI 05/780-MP-S08  
Part No : MVS1 10/800S90 S02UE obsolete, replacement MVSI 10/810-S08  
Part No : MVS1-15/1100E "S90- obsolete, replaced by MVSI 15/1100E-S02  
Part No : MVS136-660  
Part No : MVSI 05/770MP-S90 obsolete, replaced by MVSI 05/780-MP-S08, 440 V,  
60 Hz, 600 min-1  
Part No : MVSI 05/780-MP-S08  
Part No : MVSI 05/780-MP-S08, 440 V, 60 Hz, 600 min-1  
Part No : MVSI 06/1100-S08  
Part No : MVSI 06/550-S02  
Part No : MVSI 06/780-MP-S08  
Part No : MVSI 06/780-MP-S90 obsolete, replaced by MVSI 06/780-MP-S08  
Part No : MVSI 075/10000-S02  
Part No : MVSI 075/10000-S02-TS  
Part No : MVSI 075/10000E-S02  
Part No : MVSI 075/12000-S90  
Part No : MVSI 075/1310-S08  
Part No : MVSI 075/1310E-S08  
Part No : MVSI 075/14000-S02  
Part No : MVSI 075/14000-S02-TS  
Part No : MVSI 075/150-S02  
Part No : MVSI 075/150E-S02  
Part No : MVSI 075/17000-S02  
Part No : MVSI 075/17000-S02-TS

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web:  
<http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MVSI 075/1750-S08  
Part No : MVSI 075/2110-S02  
Part No : MVSI 075/2110-S02-TS  
Part No : MVSI 075/2110E-S02  
Part No : MVSI 075/22000-S90  
Part No : MVSI 075/22000-S90-TS  
Part No : MVSI 075/250-S02  
Part No : MVSI 075/250E-S02  
Part No : MVSI 075/26000-S90  
Part No : MVSI 075/30000-S02  
Part No : MVSI 075/3110-S02  
Part No : MVSI 075/3110-S02-TS  
Part No : MVSI 075/3110E-S02  
Part No : MVSI 075/3800-S02  
Part No : MVSI 075/3800-S02-TS  
Part No : MVSI 075/3800E-S02  
Part No : MVSI 075/400-S02  
Part No : MVSI 075/400E-S02  
Part No : MVSI 075/4200-S02  
Part No : MVSI 075/4200-S02-TS  
Part No : MVSI 075/4200E-S02  
Part No : MVSI 075/530-S02  
Part No : MVSI 075/5300-S02  
Part No : MVSI 075/5300-S02-TS  
Part No : MVSI 075/5300E-S02  
Part No : MVSI 075/6500-S90  
Part No : MVSI 075/6500-S90-TS  
Part No : MVSI 075/660-S08  
Part No : MVSI 075/660E-S08  
Part No : MVSI 075/6800-S02  
Part No : MVSI 075/6800-S02-TS  
Part No : MVSI 075/910-S08  
Part No : MVSI 075/910-S08, 400 V, 50 HZ, 750 RPM  
Part No : MVSI 075/910-S08-TS  
Part No : MVSI 075/910E-S02

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : MVSI 075/910E-S08  
Part No : MVSI 10-550 S02  
Part No : MVSI 10/100-S02  
Part No : MVSI 10/10000-S02  
Part No : MVSI 10/10000-S02-TS  
Part No : MVSI 10/10000E-S02  
Part No : MVSI 10/1110-S08  
Part No : MVSI 10/1110-S08 230/400VOLT, 50HZ  
Part No : MVSI 10/1110-S08, 400 V, 50 HZ, 1000 RPM  
Part No : MVSI 10/1110-S08-TS  
Part No : MVSI 10/1110E-S08  
Part No : MVSI 10/11200-S02  
Part No : MVSI 10/11200E-S02  
Part No : MVSI 10/12000-S90  
Part No : MVSI 10/13000-S02  
Part No : MVSI 10/13000-S02, 400 V, 50 HZ, 1000 RPM  
Part No : MVSI 10/13000-S02-TS  
Part No : MVSI 10/1400-S08  
Part No : MVSI 10/1400-S08 230/400VOLT, 50HZ  
Part No : MVSI 10/1400-S08 Gewicht: 66 kg 400 V, 50 Hz, 1000 min-1  
Part No : MVSI 10/1400-S08-S  
Part No : MVSI 10/1400-S08-TS  
Part No : MVSI 10/1400-S08-TS2  
Part No : MVSI 10/1400E-S08  
Part No : MVSI 10/15000-S02  
Part No : MVSI 10/15000-S02-ACC  
Part No : MVSI 10/15000-S02-TS  
Part No : MVSI 10/1610-S08  
Part No : MVSI 10/1610E-S08  
Part No : MVSI 10/17500  
Part No : MVSI 10/17500-S02  
Part No : MVSI 10/17500-S02-ACC  
Part No : MVSI 10/17500-S02-TS  
Part No : MVSI 10/19500-S02  
Part No : MVSI 10/200-890SERI obsolete,replaced by MVSI 10/200-S02

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MVSI 10/200-S02  
Part No : MVSI 10/200E-S02  
Part No : MVSI 10/2100-S08.  
Part No : MVSI 10/2100E-S08  
Part No : MVSI 10/22000-S90  
Part No : MVSI 10/22000-S90-ACC  
Part No : MVSI 10/22000-S90-TS  
Part No : MVSI 10/25000-S90  
Part No : MVSI 10/25000-S90-ACC  
Part No : MVSI 10/25000-S90-TS  
Part No : MVSI 10/2610-S02  
Part No : MVSI 10/2610-S02-TS  
Part No : MVSI 10/2610E-S02  
Part No : MVSI 10/3000-502  
Part No : MVSI 10/3000-S02, 230/460 V  
Part No : MVSI 10/3000-S02-TS  
Part No : MVSI 10/30000-S02  
Part No : MVSI 10/3000E-S02  
Part No : MVSI 10/310-S02  
Part No : MVSI 10/310-S02 FC 321KG RPM1000  
Part No : MVSI 10/310-S02-T, 330/575 V  
Part No : MVSI 10/310E-S02  
Part No : MVSI 10/3810-S02  
Part No : MVSI 10/3810-S02-TS  
Part No : MVSI 10/3810E-S02  
Part No : MVSI 10/40-S02  
Part No : MVSI 10/4700, replaced by MVSI 10/4700-S02  
Part No : MVSI 10/4700-S02  
Part No : MVSI 10/4700-S02-TS  
Part No : MVSI 10/4700E-S02  
Part No : MVSI 10/5150-S02  
Part No : MVSI 10/5150E-S02  
Part No : MVSI 10/5200, replaced by MVSI 10/5200-S90  
Part No : MVSI 10/5200-S02  
Part No : MVSI 10/5200-S02-TS

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : MVSI 10/5200-S90  
Part No : MVSI 10/5200E-S02  
Part No : MVSI 10/550 S90  
Part No : MVSI 10/550-S02 1200 MIN-1  
Part No : MVSI 10/550E-S02  
Part No : MVSI 10/5700-S02  
Part No : MVSI 10/5700-S02-TS  
Part No : MVSI 10/5700E-S02  
Part No : MVSI 10/650-S02  
Part No : MVSI 10/6500-S02  
Part No : MVSI 10/6500-S02-TS  
Part No : MVSI 10/6600-S02  
Part No : MVSI 10/6600-S02, 400 V, 50 HZ, 1000 RPM  
Part No : MVSI 10/6600E-S02  
Part No : MVSI 10/7000-S02  
Part No : MVSI 10/800-S90  
Part No : MVSI 10/8000-S90  
Part No : MVSI 10/8000-S90, 400 V, 50 HZ, 1000 RPM  
Part No : MVSI 10/8000-S90-TS  
Part No : MVSI 10/810-S02  
Part No : MVSI 10/810-S02 obsolete, replacement MVSI 10/810-S08  
Part No : MVSI 10/810-S08  
Part No : MVSI 10/810-S08, 400 V, 50 HZ, 1000 RPM  
Part No : MVSI 10/810-S08-S  
Part No : MVSI 10/810-S90 obsolete, replacement MVSI 10/810-S08  
Part No : MVSI 10/810E-S08  
Part No : MVSI 10/9000-S90  
Part No : MVSI 10/9000-S90 7,5KW, 1000D/M  
Part No : MVSI 10/9000-S90-TS  
Part No : MVSI 15-400 S02  
Part No : MVSI 15/100  
Part No : MVSI 15/100 s2  
Part No : MVSI 15/100-S02  
Part No : MVSI 15/1100-S02, 400 V, 50 Hz, 1500 min-1  
Part No : MVSI 15/1100-S90 obsolete, replace,emt MVSI 15/1100-S02

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)



Part No : MVSI 15/1100E-S02  
Part No : MVSI 15/11500-S90  
Part No : MVSI 15/1400  
Part No : MVSI 15/1400-S90 replaced by MVSI 15/1410-S02  
Part No : MVSI 15/1410 230/400 VOLT 50 HZ  
Part No : MVSI 15/1410-S02  
Part No : MVSI 15/1410E-S02  
Part No : MVSI 15/14500-S90  
Part No : MVSI 15/1710-S02  
Part No : MVSI 15/1710-S02, 230/400 V, 50 Hz, 1500 1/min  
Part No : MVSI 15/1710-S02, 400 V, 50 Hz, 1500 min-1  
Part No : MVSI 15/1710-S02-TS  
Part No : MVSI 15/1710E-S02  
Part No : MVSI 15/1720-S90  
Part No : MVSI 15/200  
Part No : MVSI 15/200-S02  
Part No : MVSI 15/200-S02, 400 V, 50 HZ, 1500 RPM  
Part No : MVSI 15/200-S90- obsolete, replaced by MVSI 15/200-S02  
Part No : MVSI 15/200/390  
Part No : MVSI 15/2000 S90 obsolete replaced by MVSI 15/2000-S02  
Part No : MVSI 15/2000-S02-TS  
Part No : MVSI 15/2000-S02.  
Part No : MVSI 15/2000E-S02  
Part No : MVSI 15/200E-S02  
Part No : MVSI 15/200T-S02  
Part No : MVSI 15/2410-S02 - OBSOLETE, REPLACED BY NEXT MODEL MVSI 15/2410-S08  
Part No : MVSI 15/2410-S08  
Part No : MVSI 15/2410E-S02  
Part No : MVSI 15/2410E-S08  
Part No : MVSI 15/3000-S08  
Part No : MVSI 15/3000E-S08  
Part No : MVSI 15/35  
Part No : MVSI 15/35-S02  
Part No : MVSI 15/35-S90, 1500 RPM, SERIA AD OBSOLETE- REPLACED BY MVSI 15/35-S02

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : MVSI 15/3810-S02  
Part No : MVSI 15/3810-S02-TS  
Part No : MVSI 15/3810-S90-NICHT MEHR LIEFERBAR! ERSETZT DURCH "MVSI 15/3810-S02"  
Part No : MVSI 15/3810E-S02  
Part No : MVSI 15/400-S02, 400 V, 50 Hz, 1500 min-1  
Part No : MVSI 15/400-S02  
Part No : MVSI 15/400E-S02  
Part No : MVSI 15/400T-S02  
Part No : MVSI 15/4300-S02  
Part No : MVSI 15/4300-S02-TS  
Part No : MVSI 15/4300E-S02  
Part No : MVSI 15/5010-S02  
Part No : MVSI 15/5010-S02-TS  
Part No : MVSI 15/5010E-S02  
Part No : MVSI 15/550 - alternative MVSI 15/550-S02  
Part No : MVSI 15/550-S02  
Part No : MVSI 15/550-S02 1800 MIN-1  
Part No : MVSI 15/550-S02, 400 V, 50 Hz, 1500 min-1  
Part No : MVSI 15/550-S90 SERIE:AB  
Part No : MVSI 15/550E-S02  
Part No : MVSI 15/6000-S02  
Part No : MVSI 15/6000-S02-TS  
Part No : MVSI 15/6000E-S02  
Part No : MVSI 15/700-S02  
Part No : MVSI 15/700-S02, 230/400 V, 50 Hz, 1500 1/min  
Part No : MVSI 15/700-S900 obsolete replaced by MVSI 15/700-S02  
Part No : MVSI 15/7000-S02  
Part No : MVSI 15/7000-S90 obsolete, replacement MVSI 15/7000-S02  
Part No : MVSI 15/700E-S02  
Part No : MVSI 15/700T-S02  
Part No : MVSI 15/80-S02  
Part No : MVSI 15/80-S02, 230/400 V  
Part No : MVSI 15/80-S02, 400 V  
Part No : MVSI 15/80-S90

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : MVSI 15/80-S90, 1500 RPM, SERIA A■' obsolete, replaced by MVSI 15/80-S02, 400 V

Part No : MVSI 15/900-S02

Part No : MVSI 15/9000-S90

Part No : MVSI 15/9500-S02

Part No : MVSI 15/9500-S02-TS

Part No : MVSI 15/9500E-S02

Part No : MVSI 15/9800-s90

Part No : MVSI 3/ 100-S90 obsolete, replaced by - MVSI 3/100-S02

Part No : MVSI 3/100-S02 3~phase

Part No : MVSI 3/100-S02, 400 V, 50 Hz, 3000 min-1

Part No : MVSI 3/100E-S02

Part No : MVSI 3/1100-S02

Part No : MVSI 3/1100-S02, 400 V, 50 Hz, 3000 min-1

Part No : MVSI 3/1100-S90

Part No : MVSI 3/1100E-S02

Part No : MVSI 3/1300-S08

Part No : MVSI 3/1300E-S08

Part No : MVSI 3/1500-S08

Part No : MVSI 3/1500E-S08

Part No : MVSI 3/1600-S02

Part No : MVSI 3/1600E-S02

Part No : MVSI 3/1800-S02

Part No : MVSI 3/1800E-S02

Part No : MVSI 3/200 S02 230/460 V, 60 Hz, 3600 min-1

Part No : MVSI 3/200-S02

Part No : MVSI 3/200-S02 220/400V, 3000 R/MIN., 018KW

Part No : MVSI 3/200-S02 230/400 V, 50 Hz, 3000 1/min

Part No : MVSI 3/200-S02, 400 V, 50 HZ, 3000 RPM

Part No : MVSI 3/200E-S02

Part No : MVSI 3/2010-S90

Part No : MVSI 3/2010E-S90

Part No : MVSI 3/2310 S90

Part No : MVSI 3/2310E-S90

Part No : MVSI 3/300-S02

Part No : MVSI 3/300-S02, 400 V, 50 Hz, 3000 min-1

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MVSI 3/300E-S02  
Part No : MVSI 3/3200-S02  
Part No : MVSI 3/4000-S02  
Part No : MVSI 3/500  
Part No : MVSI 3/500-S02  
Part No : MVSI 3/5000-S02  
Part No : MVSI 3/5000-S90  
Part No : MVSI 3/5000E-S02  
Part No : MVSI 3/500E-S02  
Part No : MVSI 3/6510-S02  
Part No : MVSI 3/700-S02  
Part No : MVSI 3/800-S02  
Part No : MVSI 3/800-S02, 230/400 V, 50 Hz, 3000 1/min  
Part No : MVSI 3/800E-S02  
Part No : MVSI 3/9000 S90  
Part No : MVSI 6/780-S08, 400 V, 50 HZ, 600 RPM  
Part No : MVSI-10/1110-S90 obsolete, replaced by MVSI 10/1110-S08  
Part No : MVSI-15/1100-S02  
Part No : MVSI-15/18-S02  
Part No : MVSI-3/200/S90  
Part No : MVSI-S90  
Part No : MVSI10/3000-S02 SERIE AA  
Part No : MVSI15/100-S02  
Part No : MVSI3/100-S02  
Part No : MVSI 10/15000-S90 ,SERIE:AA  
Part No : MVSL 3/200-S90 obsolete, replacement MVSI 3/200-S02  
Part No : MVSL-9-21900  
Part No : MVSS 15/1100-S02  
Part No : MVSS075/1310-S08  
Part No : MVSS075/150-S02  
Part No : MVSS075/2110-S02  
Part No : MVSS075/250-S08  
Part No : MVSS075/400-S02  
Part No : MVSS075/660-S08  
Part No : MVSS075/910-S08

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : MVSS10/100-S02  
Part No : MVSS10/1110-S08  
Part No : MVSS10/1400-S08  
Part No : MVSS10/1610-S08  
Part No : MVSS10/200-S02  
Part No : MVSS10/2100-S08  
Part No : MVSS10/2610-S02  
Part No : MVSS10/3000-S02  
Part No : MVSS10/310-S08  
Part No : MVSS10/40-S02  
Part No : MVSS10/550-S02  
Part No : MVSS10/810-S08  
Part No : MVSS15/100-S02  
Part No : MVSS15/1100-S02  
Part No : MVSS15/1410-S02  
Part No : MVSS15/1710-S02  
Part No : MVSS15/200-S02  
Part No : MVSS15/2000-S02  
Part No : MVSS15/2410-S02  
Part No : MVSS15/3000-S02  
Part No : MVSS15/35-S02  
Part No : MVSS15/3810-S02  
Part No : MVSS15/400-S02  
Part No : MVSS15/4300-S02  
Part No : MVSS15/550-S02  
Part No : MVSS15/700-S08  
Part No : MVSS15/80-S02  
Part No : MVSS3/100-S02  
Part No : MVSS3/1100-S02  
Part No : MVSS3/1510-S02  
Part No : MVSS3/200-S02  
Part No : MVSS3/2010-S02  
Part No : MVSS3/300-S02  
Part No : MVSS3/500-S02  
Part No : MVSS3/800-S08

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : NJ 2320 EMA C4  
Part No : No. 22  
Part No : No. 26  
Part No : No. 32  
Part No : No. 39  
Part No : Obsolete MVSI 10/800-S90-TS2 replaced by 602380  
Part No : Obsolete MVSI 10/800-S90-TS2.  
Part No : Obsolete Type MVSI 10/2000-S90 5-HZ replaced by MVSI 10/2100-S08  
Part No : Protective cover for MVSI 15/14500-S02  
Part No : SCRAP SIEVE FOR VU 38000/6-S08  
Part No : Schutzhaube fÃ¼r MVSI 10/310-S02  
Part No : TIPO MICRO M20-TR obsolete, replaced by M3-20-S02  
Part No : Type MVSI 15/80-S90 replaced by MVSI 15/80-S02  
Part No : Type: CDX18-2150  
Part No : Type: CDX18-5900 not available only the motor- OEM  
Part No : Type: MVSI 06/1100-S90 S/N: 020109691 REPLACED BY MVSI 06/1100-S08  
Part No : Type: MVSI 3/55-VS 100-AA Code:204432  
Part No : UR 10/5200-S90  
Part No : USA Code MVSS 18-2150/ EU Code MVSS 15/1100-S02  
Part No : UXM-46068-108  
Part No : VB 15/2510-D  
Part No : VM 10/6500-S90  
Part No : VM12-17600  
Part No : VMX 18-8300  
Part No : VMX18 8300  
Part No : VMX18-10900  
Part No : VU 38000/6-S08  
Part No : cdx 12-8450  
Part No : protection cover item 23 for vibrating motor ITALVIBRAS model MVSI 10/800-S90-TS2