



## FLUCOM Stock List

Part No : DN LPA20  
Part No : 0218 LPS20/20 D-N  
Part No : 0314 ETD 3074309  
Part No : 09-415-0003  
Part No : 1317 ETD30/4205  
Part No : 20-C4-B06  
Part No : 20-LO-B05  
Part No : 20-LO-B06  
Part No : 25 125 105  
Part No : 25.011.175 ETD 20/3204-R-V  
Part No : 25.125.102  
Part No : 25125101  
Part No : 25125102  
Part No : 25125104  
Part No : 25125105  
Part No : 28 011 173  
Part No : 28011173  
Part No : 30 CFT 34 4413  
Part No : 30-CFT-02  
Part No : 30-LO-B06  
Part No : 30-LO-B08  
Part No : 30/2202-MO  
Part No : 3080-500010  
Part No : 31.011.107 LPA 30/ U-N  
Part No : 31.011.108 LPA 30/D-N  
Part No : 31.011.159

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 3185-20C4B06  
Part No : 3185-B3024C28H  
Part No : 3185-B3027C28H  
Part No : 3185-CAE50-M  
Part No : 3185-ELP50-P1  
Part No : 3185-LPA30DN  
Part No : 3185-LPA30UN  
Part No : 3185-LPY30-DN  
Part No : 33.011.117 RDZ 30/D-H  
Part No : 33.011.2001  
Part No : 35 011 117  
Part No : 35 011 126  
Part No : 35 125 109  
Part No : 35.125.102  
Part No : 35125102  
Part No : 35125106  
Part No : 35125109  
Part No : 35125109- B30 27C 28H  
Part No : 4419\24VDC  
Part No : 4610  
Part No : 50-LO-B08  
Part No : 51.011.104  
Part No : 55 011 118  
Part No : 55 125 101  
Part No : 55.011.138  
Part No : 55125102  
Part No : 70-LO-B20  
Part No : 90 – LO – B06 4705  
Part No : 90.620.100  
Part No : B20 24A 18H  
Part No : B20 24C 18H  
Part No : B20-12C-18H  
Part No : B20-220A-18H  
Part No : B20-24C-28 H  
Part No : B30 110A 28H

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : B30-12C-28H  
Part No : B30-220A-28H  
Part No : B30-24C-28H  
Part No : B30-27C-28H  
Part No : B50-12C-33H  
Part No : B50-220A-33H  
Part No : B50-24C-33H  
Part No : CAE 20/P  
Part No : CAE 50-Z 4312  
Part No : CAE 70-P 2308  
Part No : CAE 70/P  
Part No : CAE20/M  
Part No : CAE50/M  
Part No : CAP20  
Part No : CAP20/M  
Part No : CAP50/M  
Part No : Coil B20 24C 18H  
Part No : DCC30/U  
Part No : ECD 30/3204  
Part No : ECD 30/3204-M0  
Part No : ECD 50/2202  
Part No : ECD20/2202  
Part No : ECD20/2202-MO  
Part No : ECD20/3204+B20-24C-18H  
Part No : ECD20/3204+B20-24C-18H.  
Part No : ECD20/3204MO+B20-24C-18H  
Part No : ECD30 /3204  
Part No : ECD30/2202  
Part No : ECD30/2202/MO  
Part No : ECD50/2202-MO  
Part No : ECP 20/22B1  
Part No : ECP 20/22B2  
Part No : ECP 20/22C1  
Part No : ECP 20/22C2  
Part No : ECP 30/22B1

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : ECP 30/22C2  
Part No : ECP20/22B2  
Part No : ECP20/22C1  
Part No : ECP30/22B1-MO  
Part No : ECP30/22B2  
Part No : ECP30/22C1  
Part No : EDP50 / D2 0808  
Part No : ELP30/P1MF  
Part No : ELP50/P1-M  
Part No : ELP70/P1  
Part No : ETD 20 3204-R-V  
Part No : ETD 20/3204  
Part No : ETD 20/3204-V  
Part No : ETD 20/4205  
Part No : ETD 30/3204  
Part No : ETD 50/3203  
Part No : ETD20/3204  
Part No : FLUCOM - CMC 30/T-L  
Part No : FLUCOM - CMW30T-L 189  
Part No : FLUCOM - LPB20-D-N  
Part No : LE PGX  
Part No : LPA 20/T-N  
Part No : LPA 20/T-N-PB  
Part No : LPA 30/D-N 4313  
Part No : LPA 30/U-N  
Part No : LPA20  
Part No : LPA20 TN-PB 4913  
Part No : LPA20/T-N  
Part No : LPA20TN-PB  
Part No : LPA30 / DN1213  
Part No : LPA30 / UN1213  
Part No : LPA30-TN  
Part No : LPA30/D-N 4313  
Part No : LPAB0/UTN  
Part No : LPB50/T-P

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : LPB50/U-P  
Part No : LPI 50/D-N  
Part No : LPI 50/Q-N  
Part No : LPS 20/20  
Part No : LPS-20/Q-N  
Part No : LPY30/DN CSL 10-B06  
Part No : Lp■ 30 d-nf  
Part No : MCD 28/2202/PB  
Part No : MCD 32  
Part No : MCD 32/2202-PS  
Part No : MCD28/2202  
Part No : MCD32 2202-PS  
Part No : N 1 ELP70 P1  
Part No : N 1 PPI30 T 24C 22H  
Part No : N 10 LPS20 20 DN  
Part No : NC  
Part No : PLP 30 /OM-24C-22H  
Part No : PLP30  
Part No : PLP30 / U-24C-22H  
Part No : PPI 30 / T -24C-22H  
Part No : RDB 30/N  
Part No : RDZ 30  
Part No : RDZ30/DH  
Part No : S30/2 400258  
Part No : S30/3 400236  
Part No : U-24C-22H  
Part No : VDE-0580  
Part No : VDT20 3202 QN  
Part No : VDT20/3202  
Part No : VDT20/3202 T-N  
Part No : VPC-12/24-DIN  
Part No : VPC-24-DIN

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)